



STEP 3 :

- Screw Mount Surface Bolt (F) to Desired Surface
- Screw Cap (D) To Surface Bolt (F)
- Push Tube (E) To Release Cable
- Cut Excess Cable (C) To Desired Length



STEP 2 :

- Feed Suspension Cable (C) Through Cap (D)
- Feed Suspension Cable (C) Into Main Body (B)
- Push Tube (E) To Release Cable



STEP 1 :

- Slide Bolt (A) Through Profile
- Tighten Down With Main Body (B)

